PALM BEACH COUNTY BOARD OF COUNTY COMMISSIONERS AGENDA ITEM SUMMARY



Meeting Date: June 5, 2007 [x]Consent []Regular []Ordinance []Public Hearing

Department: Facilities Development & Operations

I. EXECUTIVE BRIEF

Motion and Title: Staff recommends motion to approve: JOC Work Order No.07-085 with H.A. Contracting Corp., (R2005-0541) in the amount of \$214,219.53 to provide replacement of the stucco on the Admin Building at Eagle Academy in Belle Glade.

Summary: The work consists of the replacement of the existing stucco finish, including subsurface repairs, painting, and installing hurricane shutters. The stucco finish is badly deteriorated and beyond repair with numerous cracks which sustained further damage from the hurricanes. This work is required to protect this residential building from the elements. The SBE participation in this work order is 3.03%. When the participation for this work order is added to H.A.'s total participation-to-date, the resulting values are 16.1%. The SBE goals are 15%. The total construction duration is 180 days. This work will comply with all applicable local, state, and federal codes and regulations. (FD&O Admin) Countywide/District 6 (JM)

Background & Justification: The stucco finish is badly deteriorated, beyond patch repair, with numerous cracks, and the building is no longer adequately protected from the elements.

Attachments:

- 1. Location Map
- 2. Work Order
- Contractor's Cost Proposal
- V. SBE Estimate Report
- 5. Budget Availability Statement

II. FISCAL IMPACT ANALYSIS

A. Five Year Summary of Fiscal Impact:

Fiscal Year	2007	2008	2009	2010	2011
Capital Expenditures Operating Costs	240,054.78	0 0	0 0	0 0	0 0
External Revenues Program Income (County)	0	0	0 0	0	0
In-Kind Match (County)	0	0	0	0	Ö
NET FISCAL IMPACT	240,054.78	0	0	0	0
# Additional FTE Positions (Cumulative)	_	_			

Is Item Included in Current Budget? Yes X No _

3804 411-B402-4907 2,173.77

Budget Account No:

3804-411-B274-4610 58,655.94

3804-411-M027-4610 \$60,596.07 3804-411-B332-4610 \$13,765.00 3804-411-B216-4610 \$14,292.00

3804-411-B328-4610 90,572.00 240,054.78

Reporting Category _

B. Recommended Sources of Funds/Summary of Fiscal Impact:

Construction: 214,219.53 Architect/Eng: 3,213.29 Staff Costs: 1,200 21,421.95 Contingency

Total: 240,054.78

C. Departmental Fiscal Review:

III. REVIEW COMMENTS

A. OFMB Fiscal and/or Contract Development & Control Comments:

Jam Onl	5.2307	Contract Dev. and Control Species 5/24/07
OFMB	0/5/21/07	Contract Dev. and Control () 24/03
16 23 W	•	7 40

B. Legal Sufficiency:


this item complies with current County policies.

Assistant County Attorney

C. Other Department Review:

Department Director

This summary is not to be used as a basis for payment.



ATTACHMENT #/

April 18, 2007	JOC Work Order Job Order Construction Services		
	Eagle Academy - Stucco - Admin Bldg		(W)
07314.01	Eagle Academy/Administration Building	•	CORLO
J. J. 1101	38840 State Road 80, BELLE GLADE		
	ADVE		

Brief Description: Remove existing stucco finish & re-surface the Housing Bldg . Repair gable ends, extend gutter dowenspouts away from Bldg. , install hurricane shutters on all windows, and re-paint the bldg

after the new stucco finish is applied.

Contractor:

HA Contracting Corp.

9500 NW 12th Street

Miami, FL 33172

R-2005-0541 Dated March 15, 2005

AMOUNT:

Contract:

\$ 214,219.53

DISTRICT:

Funding:

 $3804\text{-}411\text{-}B274\text{-}4610\ \$75045.94;\ 3804\text{-}411\text{-}M027\text{-}4610\ \$60596.07;$

3804-411-B332-4610 \$13765.; 3804-411-B216-6504 \$14292.;

3804-411-B328-4610 \$76355.77

JOC Work Order #: 07-085

Project Duration: 61 Months

(Liquidated damages will apply)

Approval Signatures

Andre Gonzalez, Project Coordinator	4/18/s7 Date
Audrey Wolf, Director	1 Ammy Work 9/4/07
Facilities Development & Operations	Date
Chair	(NOT REQUIRED FOR PROJECTS <\$100,000 OR >\$200,000)
Contract Review Committee	Date
Approved as to form and legal sufficiency	
County Attorney	Date
Addie L. Greene, Chairperson	
Board of County Commissioners	Date

President	80 July 4-18-07	
HA Contracting Corp.	Date	

COPY: Project File

Procurement & Project Implementation Group 3323 Belvedere Rd, Bldg 509, West Palm Beach, FL 33406

ATTACHMENT #2

Job Order #:

07314.01

Job Order Title:

Eagle Academy - Stucco - Admin Bldg

Date:

April 30, 2007

Section	Total
Section 01 - General Requirements	\$117,597.38
Section 02 - Site Work	\$3,751.16
Section 03 - Concrete	\$53.25
Section 04 - Masonry	\$961.63
Section 05 - Metals	\$15,511.80
Section 07 - Thermal & Moisture Protection	\$1,479.44
Section 09 - Finishes	\$64,408.34
Section 10 - Specialties	\$7,188.21
Section 18 - Non-PrePriced	\$3,268.32
Job Order Proposal Total	\$214,219.53

This work order proposal total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding of the line totals and sub-totals.

4/30/2007

Proposal Review Summary - CSI

Page 1 of 1

ATTACHMENT #3

Job Order Contract Proposal Review

Date

April 30, 2007

Re:

Job Order #:

07314.01

Title:

Eagle Academy - Stucco - Admin Bldg

Contractor:

Review:

HA Contracting Corp.
EAGLE ACADEMY - STUCCO - ADMIN. BLDG. - 4/1/2007 5:40:12PM

Proposal Value:

214,219.53

Sect.	Item	Mod.	UOM	Description	on								Line Total
Sectio	n 01												
01352	1091		HR	These Iter		quested	The CTC Include Specifically By						2,591.48
			1	4-0-11	Quantity		Unit Price		Facto			Total	
				tallation	80.00	X	31.45	X	1.030	0 =		2,591.48	
01352	1201		HR		it. dish ,3 - reg		s. ms In The CTC	Includ	le Appropriate	Costs	To Cover		040.0
01002	1201		1113	Labor. The	ese Items Will Covered In Th	Be Req	uested Specific						310.8
			lne	tallation	Quantity		Unit Price		Facto			Total	
					16.00	Х	18.86	X	1.030	0 =		310.81	
01352	1241			gle logo trace		no lo Th	ne CTC Include	Annra	prieto Costo	Fo Cove	a Labar		
	1241		HR	These Iten	ns Will Be Red ed In The CTC	quested	Specifically By		wner For Mis	cellane		,	56,973.42
			Ins	tallation	Quantity	.,	Unit Price 26.34		Facto 1.030		. 5	Total 6,973,42	
					2,100.00 cco, c. bead,e	X vn. it	20.04	X	1.030	0	J	0,913.42	
01352	1241		PCT	For Forem	· _ · · · · · · · · · · · · · · · · · ·	хр. ј г.							1,427.58
01002	1271		101						. .			-	1,427.30
			Inst	tallation	Quantity 1,050.00	v	Unit Price 1.32	x	Facto 1.030			Total 1,427.58	
01352	1251		HR			X s In The	e CTC Include					1,427.00	1 700 01
	1231		HIX	These Item		uested	Specifically By						1,782.81
			lmat	allatian	Quantity		Unit Price		Facto			Total	
				tallation	48.00	Χ	36.06	X	1.030) =		1,782.81	
04050	4004			Region Co		. 1 in a 14	ama in The CT	Clash	ida Amerancia	to Cont	To Cour	~~	
01352	1281		HR	Labor, The	se Items Will Covered In Th	Be Requ	ems In The CT uested Specific		The Owner F	or Misc		5	1,427.82
			Inst	allation	Quantity		Unit Price 22.45	х	Facto 1.0600			Total 1,427.82	
				lash at gable	60.00	X	22.70	. X	1.000			1,727.02	
01352	1501	4	HR	Laborer, No These Item	ote: Line Item:	uested :	CTC Include A Specifically By						5,402.14
					Quantity		Unit Price		Facto	r ,		Total	
				allation	320.00	X	16.39	X	1.0300) =		5,402.14	
					s,mulch, R/R								
)1352	1501		HR	These Item		uested \$	CTC Include A Specifically By						8,440.85
					Quantity		Unit Price		Facto			Total	
				allation	500.00	Х	16.39	Χ.	1.0300) =	3	3,440.85	
							d blast sand/fir	nal clea	an up /grade				
1520	4012		МО	в хв х 20'	Storage Con	tainer					* .		511.02
				_11_4:	Quantity		Unit Price		Facto			Total	
			Insta	allation	3.00	X	165.38	Х	1.0300	_ = .		511.02	

30 April 2007

Page 1 of 5

			Quantity	Unit Price		Factor	Total	
		Installation	2.00	x 75.00		1.0300 =	154.50	
01540	1101	CCF Scaffolding (CCF / Mor				5' Wide x 7' Long Se		25,090.80
			Quantity	Unit Price		Factor	Total	
		Installation	580.00	x 42.00	^\	1.0300 =	25,090.80	
01540	1201	CCF Scaffolding Accessorie	s. Cost Include	Dismantling - Height s Both Erection And Unit Price	l Dismantli	Per CCF Of Scaffoling ng Of Scaffolding Factor	ding And Total	7,150.88
		Installation	Quantity 580.00	x 11.97		1.0300 =	7,150.88	
01560	4001			^		osts At 8' On Center		428.48
71300	4001	LF remperary						72010
		Installation	Quantity	Unit Price		Factor 1.0300 =	Total 428.48	
24.500	7400		520.00	^	^	flectorized Rails Eac		3,625.60
01560	7129 ·	WK Type II Tra						3,023.00
		Installation	Quantity	Unit Price		Factor	Total 3,625.60	
			320.00	^	×	1.0300 =	3,023.00	4.057.70
01590	1153	MO 42" x 60" x	30' High Platfor	rm, 1000#				1,357.73
			Quantity	Unit Price		Factor	Total	
		Installation	1.00	x 1,318.18	х	1.0300 =	1,357.73	
		Lift for painters			· · · · · · · · · · · · · · · · · · ·			100.40
1590	1303	MO 1 Ton 20' L	ift Hoist, Chain,	, Manual				490.49
			Quantity	Unit Price		Factor	Total	
		Installation	2.00	x 238.10		1.0300 =	490.49	
	4126					Equipment) > 250 H	Р	430.97
)1591			Dolivory Foo I	Delivery, Set-up And	Return			
)1591		Equipment	•			Factor	Lotal	
)1591			Quantity	Unit Price		Factor 1.0300 =	Total 430.97	
)1591		Installation Lift	•	Unit Price		Factor 1.0300 =		
		Installation	Quantity	Unit Price			430.97	17,597.38
Section	1 02	Installation Lift	Quantity 1.00	Unit Price x 418.42	x	1.0300 = Subtota	430.97	
	1 02 1201	Installation Lift	Quantity 1.00	Unit Price	x	1.0300 = Subtota	430.97	17,597.38 447.43
Section		Installation Lift	Quantity 1.00	Unit Price x 418.42	x estruction N	1.0300 = Subtota Materials Factor	430.97	
Section		Installation Lift CY Dump Fee, Installation	Quantity 1.00 Traditional Mat Quantity 80.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43	x estruction M	1.0300 = Subtota	430.97	
Section		Installation Lift CY Dump Fee, Installation	Quantity 1.00 Traditional Mat Quantity 80.00	Unit Price x 418.42 terials, Building Cor Unit Price	x estruction M	1.0300 = Subtota Materials Factor	430.97	
Section 02119	1201	Installation Lift CY Dump Fee, Installation	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43	x estruction M x	1.0300 = Subtota Materials Factor	430.97 I for 01 \$1 Total 447.43 Total	447.43
Section 02119	1201	Installation Lift CY Dump Fee, Installation	Quantity 1.00 Traditional Mat Quantity 80.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 n Unimproved Road	struction M	1.0300 = Subtota Materials Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43	447.43
Section 02119	1201	Installation Lift CY Dump Fee, Installation CYM Hauling Up	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 n Unimproved Road	x estruction N x s	1.0300 = Subtota Materials Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total	447.43
Section 122119 122119	2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier,	terials, Building Cor Unit Price X 5.43 n Unimproved Road Unit Price X 0.26 For Plant Bed Prep	x struction N x s x s	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total	447.43 321.36
Section 122119 122119	2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity	terials, Building Cor Unit Price X 5.43 Unit Price X 0.26 For Plant Bed Prep	x sstruction N x s	1.0300 = Subtota Materials Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36	447.43 321.36
Section 02119 02119 02119	1201 2002 1023	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 Unimproved Road Unit Price x 0.26 For Plant Bed Prep	x struction N x s x anation	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36	447.43 321.36
Section 122119 122119	2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric	Quantity 1.00 Traditional Mate Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss	terials, Building Cor Unit Price x 5.43 n Unimproved Road Unit Price x 0.26 For Plant Bed Prep Unit Price Unit Price x 0.26	x sstruction N x s x s x paration	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43 Total 321.36 Total 23.90	321.36
Section 02119 02119 02119	1201 2002 1023	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 Unit Price x 0.26 For Plant Bed Prep Unit Price x 0.86	x s x s x s aration	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43 Total 321.36 Total 23.90 Total	321.36
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 it Moss Quantity 260.00	terials, Building Cor Unit Price X 5.43 To Unimproved Road Unit Price X 0.26 For Plant Bed Prep Unit Price X 0.80 Unit Price X 0.80 Unit Price X 0.80	x ssruction N x s x x x aration	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43 Total 321.36 Total 23.90	321.36 23.90 591.84
Section 02119 02119 02119	1201 2002 1023	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Osoil By Hand F	terials, Building Cor Unit Price X 5.43 Unimproved Road Unit Price X 0.26 For Plant Bed Prep Unit Price X 0.80 Unit Price X 2.21 rom Stockpile	x ss x s x paration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43 Total 321.36 Total 23.90 Total 591.84	321.36
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Osoil By Hand F	terials, Building Cor Unit Price X 5.43 n Unimproved Road Unit Price X 0.26 For Plant Bed Prep Unit Price X 0.80 Unit Price X 2.21 rom Stockpile Unit Price Unit Price X 1.27	x ss x saration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43 Total 321.36 Total 23.90 Total 591.84 Total	321.36 23.90 591.84
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top Installation	Quantity 1.00 Traditional Mate Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Desoil By Hand For Quantity 10.00	terials, Building Cor Unit Price X 5.43 Unimproved Road Unit Price X 0.26 For Plant Bed Prep Unit Price X 0.80 Unit Price X 2.21 rom Stockpile	x ss x s x paration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$17 Total 447.43 Total 321.36 Total 23.90 Total 591.84	321.36 23.90 591.84
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top	Quantity 1.00 Traditional Mate Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Desoil By Hand For Quantity 10.00	terials, Building Cor Unit Price X 5.43 Unit Price X 0.26 For Plant Bed Prep Unit Price X 0.86 Unit Price X 1.273	x sstruction N x s v caration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36 Total 23.90 Total 591.84 Total 131.12	321.36 23.90 591.84
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top Installation SF Top Dress	Quantity 1.00 Traditional Mate Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Desoil By Hand For Quantity 10.00	terials, Building Cor Unit Price X 5.43 Unit Price X 0.26 For Plant Bed Prep Unit Price X 0.80 Unit Price X 12.73 Unit Price X 12.73 Unit Price X 12.73	x sstruction N x s x caration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36 Total 23.90 Total 591.84 Total 131.12 Total	321.36 23.90 591.84
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top Installation SF Top Dress Installation	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Dosoil By Hand F Quantity 10.00 By Hand Quantity 520.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 Unit Price x 0.26 For Plant Bed Prep Unit Price x 0.80 Unit Price x 12.73 Unit Price x 12.73	x ss x saration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36 Total 23.90 Total 591.84 Total 131.12	321.36 23.90 591.84 48.20
Section 02119 02119 02810	1201 2002 1023 2002	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top Installation SF Top Dress Installation	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Dosoil By Hand F Quantity 10.00 By Hand Quantity 520.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 Unit Price x 0.26 For Plant Bed Prep Unit Price x 0.80 Unit Price x 12.73 Unit Price x 12.73	x sstruction N x s x caration x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36 Total 23.90 Total 591.84 Total 131.12 Total	321.36 23.90 591.84
Section 02119 02119 02810 02810	1201 2002 1023 2002 3202	Installation Lift CY Dump Fee, Installation CYM Hauling Up Installation SY Filter Fabric Installation CF Mulch, Pea Installation CY Spread Top Installation SF Top Dress Installation	Quantity 1.00 Traditional Mat Quantity 80.00 To 15 Miles Or Quantity 1,200.00 c Weed Barrier, Quantity 29.00 It Moss Quantity 260.00 Dosoil By Hand F Quantity 10.00 By Hand Quantity 520.00	Unit Price x 418.42 terials, Building Cor Unit Price x 5.43 Unit Price x 0.26 For Plant Bed Prep Unit Price x 0.80 Unit Price x 12.73 Unit Price x 12.73	x sstruction N x s x variation x	1.0300 = Subtota Materials Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 = Factor 1.0300 =	430.97 I for 01 \$1 Total 447.43 Total 321.36 Total 23.90 Total 591.84 Total 131.12 Total	321.36 23.90 591.84 48.20

Description
For Delivery, Each Way, Add

Page 2 of 5

Line Total

154.50

Sect.

01520

ltem

4012

Mod.

EΑ

Sect.	Item	Mod.	UOM	Descripti	on						Line Tota
02820	3901		MSF	1" Deep, E	Bahia Argentine	Sod,	Under 1,000 SF	On Leve	el Ground		895.6
			Ins	tallation	Quantity 2.50	x	Unit Price 347.84	X	Factor 1.0300 =	Tota 895.69	
				d repair							
02831	1213		EA	Container,	3 Gallon, Shru	ıb Plan					773.1
			Ins	tallation	Quantity 60.00	х	Unit Price 12.51	x	Factor 1.0300 =	Tota 773.12	
02833	2001		EA	Hibiscus -	'Anderson Cre	pe', 3 (Gallon				275.0
,			Ins	tallation	Quantity 60.00	x	Unit Price 4.45	x	Factor 1.0300 =	Tota 275.01	
~ ··	^^								Subtotal	for 02	\$3,751.16
Sectio	n 03 5401		EA	Precast C	oncrete Splach	Blocks	s, Standard Size				53.2
03414	5401		EA	i recast o		DIOCKS			Factor	Tota	
			Ins	tallation	Quantity 10.00	x	Unit Price 5.17	Х	Factor 1.0300 =	Tota 53.25	
C4i-	. 04				Tanana				Subtotal	for 03	\$53.2
Sectio 04170	11 U4 4601		EA	Seismic C	lip With 9 Gau	ne Con	tinuous Wire			···	961.6
04170	4001		LA		Quantity	,	Unit Price		Factor	Tota	
***************************************			Ins	tallation	240.00	Х	3.78	х	1.0600 =	961.63	
Section	n 05							7	Subtotal	for 04	\$961.63
05502	3001		EA	1/4" Flush	Self Drilling Ar	nchor 1	-1/4" Min Depth	In Concr	ete		15,511.8
			lnei	allatian	Quantity		Unit Price		Factor	Tota 15,511.80	
	·	-	insi	allation	3,000.00	Х	5.02	Х	1.0300 = Subtotal		\$15,511.80
Section	n 07							•	Subtotal	101 03	φ10,011.00
07920	3001		CLF	Latex Cau	k And Seal, 1/4	4"x1/4"	Joint				1,479.4
					Quantity		Unit Price		Factor	Tota	1
			Inst	allation	34.15	x	42.06	x	1.0300 =	1,479.44	
Castia	OO								Subtotal	for 07	\$1,479.44
Section 09205	2102		SY	3.4# Metal	Lath (1.54 kg)	. On Fu	irred Wall Or St	uds, Incl	uding Felt.		1,562.9
55255	2702		•		Quantity	,	Unit Price		Factor	Tota	
			Inst	allation	150.00	x	9.83	x	1.0600 =	1,562.97	
00005	8103		LF	Casing Be	ad, Expanded I		Vinyl				2,643.19
09205							Unit Price		Factor	Tota	<u>†</u>
09205					Quantity		Office From				1
09205			Inst	allation	Quantity 1,820.00	х	1.41	х	1.0300 =	2,643.19	
	8105		Inst	allation Corner Bea	1,820.00	×		X		2,643.19	
	8105		LF	Corner Bea	1,820.00	<u>x</u>	1.41 Unit Price		1.0300 =	Tota	677.99
	8105		LF	Corner Bea	1,820.00 ad, Vinyl Quantity 544.00	x	1.41 Unit Price 1.21	x	1.0300 = Factor 1.0300 =	Tota 677.99	677.9
09205	8105		LF	Corner Bea	1,820.00 ad, Vinyl Quantity 544.00 oat Finish, 3 Co	x	Unit Price 1.21 Including Lath	x	1.0300 = Factor 1.0300 = Note: Interior or exter	Tota 677.99 ior, one	677.99 36,589.72
09205	·		LF Inst	Corner Bea allation Stucco, Flo	1,820.00 ad, Vinyl Quantity 544.00 oat Finish, 3 Co	x pats, 1"	1.41 Unit Price 1.21	x and Felt	1.0300 = Factor 1.0300 = Note: Interior or exter Factor	Tota 677.99	677.99 36,589.72
09205 09205 09220 09250	·		LF Inst	Corner Bea allation Stucco, Flo side. allation 5/8" Mold A	1,820.00 ad, Vinyl Quantity 544.00 out Finish, 3 Co Quantity 8,300.00	x pats, 1"	Unit Price 1.21 Including Lath a Unit Price 4.28	x and Felt	1.0300 = Factor 1.0300 = Note: Interior or exter	Tota 677.99 ior, one Tota 36,589.72	677.99 36,589.72
09205 09220	1104		LF Inst	allation Stucco, Floside. allation 5/8" Mold Areinforced.	1,820.00 ad, Vinyl Quantity 544.00 out Finish, 3 Co Quantity 8,300.00	x pats, 1"	Unit Price 1.21 Including Lath a Unit Price 4.28 Plus Fireguard Unit Price	x and Felt x Board (1	1.0300 = Factor 1.0300 = Note: Interior or exter Factor 1.0300 = 5.875 mm) Note: Mes	Tota 677.99 ior, one Total 36,589.72 sh	677.99 36,589.72 1,745.82
09205 09220	1104		LF Inst	Corner Bea allation Stucco, Flo side. allation 5/8" Mold A	1,820.00 ad, Vinyl Quantity 544.00 pat Finish, 3 Co Quantity 8,300.00 And Mildew Res	x pats, 1"	Unit Price 1.21 Including Lath a Unit Price 4.28 Plus Fireguard	x and Felt	1.0300 = Factor 1.0300 = Note: Interior or exter Factor 1.0300 = 5.875 mm) Note: Mes	Tota 677.99 ior, one Tota 36,589.72 sh	677.99 36,589.72 1,745.82

Page 3 of 5

Sect.	Item	Mod.	UOM	Descri	ption							Line Total
09250	1504		PCT	For Wa	all Height > 12' To	20' (> 3	3.6 m To 6 m), A	\dd				35.78
		·			Quantity		Unit Price		Factor		Total	
			lr.	nstallation	675.00	×	0.05	x	1.0600	=	35.78	
09910	1601		SF	Paint E	xterior Stucco Su	rfaces	One Coat Prime	r, Brush	Work			2,855.16
					Quantity		Unit Price		Factor		Total	,
			lr	nstallation	8,400.00	x	0.33	x	1.0300	=	2,855.16	
09910	1606		SF	Paint E	xterior Stucco Su	rfaces,	Two Coats Pain	t, Brush/	Roller Work			4,585.56
					Quantity		Unit Price		Factor		Total	
			lr	nstallation	8,400.00	х	0.53	x	1.0300	=	4,585.56	
09910	2201		SF	Paint E	xterior Drywall/Pla	aster C	eiling, 1 Coat Pri	mer, Bru	ish Work			74.32
					Quantity		Unit Price		Factor		Total	
			li	nstallation	328.00	x	0.22	x	1.0300	=	74.32	
09910	2206		SF	Paint E	xterior Drywall/Pla	aster C	eiling, 2 Coats P	aint, Bru	sh/Roller Wo	rk		118.24
					Quantity		Unit Price		Factor	. '	Total	
			lr	nstallation	328.00	x	0.35	X	1.0300	=	118.24	
09910	4104		LF	Paint M	letal Door Frame	And Tri	m, 1 Coat Prime	r, Brush	/Roller Work			43.96
					Quantity		Unit Price		Factor		Total	
			İr	nstallation	97.00	x ,	0.44	x	1.0300	= .	43.96	
09910	4106		LF	Paint N	letal Door Frame	And Tri	m, 2 Coats Pain	t, Brush/	Roller Work			81.93
					Quantity		Unit Price		Factor		Total	
			· Ir	nstallation	97.00	x	0.82	x	1.0300	=	81.93	
09910	4214		EA	Paint E	xterior Door, Both		, 1 Coat Primer,	Brush V				193.65
					Quantity		Unit Price		Factor		Total	
			lr	nstallation	9.00	х	20.89	x	1.0300	= '	193.65	
09910	4216		EA	Paint E	xterior Door, Both		, 2 Coats Paint,					351.43
00010	12.10		_, 、		Quantity		Unit Price		Factor		Total	
			lr	nstallation	9.00	x	37.91	x	1.0300	= .	351.43	
09910	6213		LF		Iteel Pipes 4" Diar				1.0000			86.17
09910	0213		LIT	, ante	•	notor, v					Total	
			11	nstallation	Quantity	.,	Unit Price 0.47	x	Factor 1.0300	==	Total 86.17	
00040					178.00 Steel Pipes 4" Diar	X		<u> </u>	1.0300			165.01
09910	6233		LF	Failt	• •	ileter,					-	
			1.	nstallation	Quantity		Unit Price 0.90		Factor	_	Total 165.01	
					178.00	X		X andina A	1.0300		103.01	
09920	1351		SF	Paint ir	nterior Concrete M	iasonry	Units, T Coat B	onaing A	igeni, brush			2,393.72
					Quantity		Unit Price		Factor	_	Total	
				nstallation	8,300.00	X	0.28	X	1.0300		2,393.72	
					it at exterior block		1 . ((- /\)					00.44
09925	6007		EA	Over 1	2" High, Hand Pai	nt, Per	Letter/Number					30.41
					Quantity		Unit Price		Factor	_	Total	
				nstallation	12.00	Х	2.46	×	1.0300	-	30.41	
				School nam		11	10 000 To 10	000 DC	NI ,			2.024.47
09945	1106		SF	Water	Blast Concrete Or	Masor		2,000 PS) l			2,821.17
				4 11 42	Quantity		Unit Price		Factor	_	Total	
				nstallation	8,300.00	X	0.33	×	1.0300		2,821.17	
09945	1108		SF	Sand E	Blasting Concrete	Or Mas	onry					7,352.14
					Quantity		Unit Price		Factor		Total	
				nstallation	8,300.00	Х	0.86	X	1.0300	=	7,352.14	
									Su	btotal for	r 09	64,408.34
Section	n 10											
10420	2001		SF	Porcela	ainized Steel Engr	aved P	laque Includina	Emblem	Size 1-4 SF I	Each		2,600.81
10720	2001		O,		_		Unit Price		Factor		Total	·
			11	nstallation	Quantity	~	339.39	x	1.0300	= '	2,600.81	
				Allowance	7.44	×	220.00	^	1.0000		,====.	
				Owance			·					

30 April 2007

Page 4 of 5

Sect.	Item	Mod.	UOM	Descripti	on						Line Total
10715	2201		SF	22 Gauge	Galvanized St	eel Hur	ricane Panels				3,646.36
					Quantity		Unit Price		Factor	Tota	
			ln:	stallation	592.00	Х	5.98	X	1.0300 =	3,646.36	
10715	5201		LF	H-Header	Storm Panel T	rack					460.21
			÷		Quantity		Unit Price		Factor	Tota	
			Ins	stallation	91.00	X	4.91	x	1.0300 =	460.21	
10715	5204		LF	Stud Angl	e Storm Panel	Track					480.83
					Quantity		Unit Price		Factor	Tota	
			ins	stallation	91.00	x	5.13	х	1.0300 =	480.83	
									Subtota	for 10	\$7,188.21
<u>Section</u>	า 18					, ,			· .		·
18000 👢	2019	100 A	ea	Dumpster		100		ing an area of the	ALL MARKET PROPERTY		3,268,32
		rae stra		al an all a	Quantity		Unit Price	CADE 3	Factor	Tota	3 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
NPP Tas	k		ins	stallation	4.00	X.	817.08	Χ.	1.0000 =	3,268.32	
									Subtota	for 18	\$3,268.32

Contractor Proposal Review Total

\$214,219.53

This work order proposal total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding of the line totals and sub-totals.

DATE	GC 06 - SBE Estimate							
April 18, 2007								
Job# 07314.01 Loc# 1098	Eagle Academy/Administration Building Eagle Academy - Stucco - Admin Bldg							
SUBMITTED BY	HA Contracting Corp. 9500 NW 12th Street Miami, FL 33172	Contract: R-2005-0541 Awarded: 03/15/2005						

Proposal Value:

\$ 214,219.53

Contractor/Sub-Contractor	Trade	SBE Status	SBE \$	% of Job
BK Electric				
Sampson Protective Coatings and		SBE-Non MWBE	6,500.00	6,500.00

Caulking

	Total estimate SBE participation		3.03%	
,				
0%	Estimated Participation	100%		

. . /

Page 1 of 1

Budget Availability Statement

REQUESTED BY: Andre Gonzalez

REQUEST DATE: April 02, 2007

PROJECT TITLE	Eagle Academy - Stu	cco - Admin Blag	Project No: 0/314.01	
LOCATION#: 109	8			
	=	ny/Administration Building		
ORIGINAL CONT	RACT/ANNUAL AMOUI	NT:	BCC RESOLUTION # / DATE:	
	T ARREST (LIAILIE		R-2005-0541 dated 03/15/2005	
	E ORDER AMOUNT: E ORDER NUMBER:	Work Order #: 07-085		
	ONSULTANT NAME:	HA Contracting Corp.		
		SCOPE OF SERVICES TO I	NE DROWINGS BY THE	
CONSULTANT/CO	NTRACTOR: tucco finish & re-surface	Admix, the Housing Bldg . Repair ga	able ends, extend gutter dowenspouts away bldg after the new stucco finish is applied.	
nom blug. , m otair	TUTTICATIO GIUNNIS CIT AII-	windows, and re-paint the t	nug after the new studen music is applied.	
WILL THIS AME	IDMENT CHANGE THE	ESTIMATED COST OF TH	E PROJECT? Yes	
IF YES, PROVIDE	ESTIMATES OF THE N	EW COSTS:		
CONSTRUCTION		214,219.53		
ARCHITECT/ENGI	NFFR	,	% WORK ORDER AMOUNT FOR TGG FEE	
	14 2 1 3	•	WORK ONSERVAMOSTY FOR TOO TEE	
*STAFF COSTS	·	1,200.00		
EQUIPMENT/OTH	±K	0.00		
CONTINGENCY		21,421.95		
	TOTAL:	\$240,054.78		
* By signing this RA	S your department agree	as to those staff costs and w	our account will be charged upon receipt of this	
			nal staff charges will be billed.	
nvin aum 1 aaavn			TO SOURCE (CANDELL AND THE FIRST AND THE	
800GET ACCOUN 7- 111-4-282 (7	TNUMBERS (IDENTIF)	ALL SOURCES): FUNDIN	G SOURCE (CHECK ALL THAT APPLY) FEDERAL/DAVIS BACON AD VALOREM OTHER	
3804-411-1	1627- 4610	10501-07	FEDERAL/DAVIS BACON	N
3 3804 - 411 - x	3332 - 4610 -	- 413.765.00	AD VALOREM	
4 3804 - 411 - E	216-6504 -	- \$ 14, 292.00	OTHER	
(D) J 004 - 711	DJ&8-4610 -			
SUPPLEMENTAL A	GREEMENT TO BE AP	PROVED BY:	BCC (WO > \$100,000)	
ANTICIPATED DA'	TE OF APPROVAL:ASAI	P		
	1	Co. A	4/4	1/00
BAS APPROVED B	1: Jayr		DATE:	/
ENCUMBRANCE N	UMBER:			
			RECEIVED	
		1		

ATTACHMENT #5

APR - 5 2007

PALM BEACH COUNTY P.P.I.G.

PHONE#: (561) 233-2037