
PALM BEACH COUNTY BOARD OF COUNTY COMMISSIONERS AGENDA ITEM SUMMARY



Meeting Date: April 15, 2008

[X]Consent []Ordinance [] Regular [] Public Hearing

Department: Facilities Development & Operations

I. EXECUTIVE BRIEF

Motion and Title: Staff recommends motion to approve: JOC Work Order No. 08-071 with Holt Contractors, Inc., (R2007-0947) in the amount of \$309,931.14 to provide interior renovations to create a hurricane rated interior space for the 911 Dispatch Center at PBSO Administration Building.

Summary: The work consists of the interior "hardening" of the walls and doors to create approximately 9,000 sf of interior space that will be hurricane resistant, including roll-down doors in the hallways, an independent HVAC system and emergency power. This project was funded from the Hurricane Hardening account established in 2007 and in large part allowed for the FY '08 cancellation of a future \$20,000,000 EOC Expansion Project. In addition, in FY '07 \$8,000,000 was swept from the Hurricane Hardening account to the General Fund. The SBE goals are 15%. The SBE participation in this Work Order is 100%. When the participation for this Work Order is added to Holt's total participation-to-date, the resulting values are 100%. The total construction duration is 180 days. (FD&O Admin) <u>Countywide/District 2</u> (JM)

Background & Justification: Prior to FY '08 it was planned to expand the EOC to accommodate PBSO's 911 Dispatch Center to provide that function with a hurricane hardened facility. Included in the EOC Expansion project were renovations to create functional activation support space. As part of the FY '08 CIP re-evaluation, the EOC Expansion project was canceled (\$20,000,000) and activation support space was included in the Four Points Renovation project. Creating a hurricane hardened facility for PBSO 911 Dispatch was to be accomplished via a renovation of their existing and future space with the PBSO Administration Building.

The renovations will allow the 911 Dispatch Center to remain in operation during and immediately after hurricanes. These renovations will provided an interior safe work environment even if the perimeter is breached.

Attachments:

- 1. Location Map
- 2. Work Order
- 3. Contractor's Cost Proposal
- 4. SBE Estimate Report
- 5. Budget Availability Statement

Recommended by	+ Anny WOLF	3/22/08	
-	Department Director	Date	
Approved by:	, tail uleur	4/10/08	
/	County Administrator	Date	
	0		

II. FISCAL IMPACT ANALYSIS

A. Five Year Summary of Fiscal Impact:

Fiscal Year	2008	2009	2010	2011	2012
Capital Expenditures Operating Costs	\$351,573.22	2 0	0	0	0
External Revenues	0	0	0	0	0
Program Income (County)	0	0	0	0	0
In-Kind Match (County)	0	0	0	0	0
NET FISCAL IMPACT	\$351,573.25	20	0	0	0
<pre># Additional FTE Positions (Cumulative)</pre>	_		_	_	
Is Item Included in Current Bu	udget? Yes <u>X</u>	<u>No</u>			

Budget Account No: 3804-411-B405-01-4907

Reporting Category ____

B. Recommended Sources of Funds/Summary of Fiscal Impact:

\$ 309,931.14 Construction Architect 4 648 costs Staff 6,000. OO 30,993 Ċ 11 aen au 22 351. 72 C. Departmental Fiscal Review: 31-08

III. REVIEW COMMENTS

A. OFMB Fiscal and/or Contract Development & Control Comments:

17/20 Contract Dev. and Control

This item complies with current County policies.


B. Legal Sufficiency:

sistant Attorney

C. Other Department Review:

Department Director

This summary is not to be used as a basis for payment.



ATTACHMENT # 1

March 19, 2008	JOC Work Ord Job Order Construction S		THE ACH CO
07616	PBSO - 911 Hardening CJC Bldg A, Administration, 3228 Gun Club Road 3228 Gun Club Road, WEST PALM BEACH		FLORIDA
Brief Description	Provide renovations required to create a hurricane ra Bridge Design/Gartek Engineering.	ted interior space for 911, per	the plans by
Contractor: Contract:	Holt Contractors, Inc. 8161 NW 51st Place Coral Springs, FL 33067 R-2007-0947 Dated June 19, 2007		
AMOUNT:	\$ 309,931.14	DISTRICT: 2	
Funding:	3804-411-B405-01-4907		
JOC Work Order #	: 08-071		
Project Duration:	6 Months (Liquidated damages will apply)	•	·

Approval Signatures

For Daniel Racette, Project Coordinator	adayn 3/19/07 Date
Audrey Wolf, Director	Ahmen Wolf 3/25/08
Facilities Development & Operations	
Chair	(NOT REQUIRED FOR PROJECTS <\$100,000 OR >\$200,000)
Contract Review Committee	Date
Approved as to form and legal sufficiency	
County Attorney	Date
Addie L. Greene, Chairperson	
Board of County Commissioners	Date

President	Mulbert	3-19-08
Holt Contractors, Inc.		Date

COPY: Project File

JOC Work Order

Page 1 of 1 3/19/2008

Procurement & Project Implementation Group 2633 Vista Parkway, West Palm Beach, FL 33411-5607



Job Order Contract Proposal Review - CSI Summary

DateMarch 18, 2008Job Order Number:07616Job Order Name:PBSO - 911 HardeningReview:PBSO - 911 Hardening - 3/17/2008 12:59:48PM

Section 01	Subtotal for 01	\$23,016.81
Section 05	Subtotal for 05	\$33,641.82
Section 06	Subtotal for 06	\$27,871.43
Section 07	Subtotal for 07	\$1,581.44
Section 08	Subtotal for 08	\$3,398.21
Section 09	Subtotal for 09	\$127,661.60
Section 15	Subtotal for 15	\$59,232.16
Section 16	Subtotal for 16	\$33,527.67
Dren cool Deview Total		\$309 931 14

Proposal Review Total

This job order proposal total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding of the line totals and sub-totals.

Proposal Review - CSI Summary



Page 1 of 1 3/18/2008

5309,931.14

Job Order Contract Proposal Review - CSI Detail

Date

DateMarch 18, 2008Job Order Number: 07616 Job Order Name: PBSO - 911 Hardening **Review:** PBSO - 911 Hardening - 3/17/2008 12:59:48PM

	Sect.	ltem	Mod.	UOM	Descripti	on						Line Total
Sec	tion 01		s de statue.				an ing Tagan			(11) and the second second second		
1	01510	2017		EA	Service	oumpster (13 To To Deliver And er And Disposal	Pick-u	acity) "Construc ip Of Dumpster,	tion De Hauling	bris" Note: Price Include g Of Debris, Rental Of	es	\$3,483.00
				Inst	allation	Quantity 5.00	x	Unit Price 675.00	х	Factor 1.0320 =	Total \$3,483.00	
2	01540	3003		MO						, Railings, Etc., (5' Wide	X 7'	\$918.80
					Long Se	ction) Quantity		Unit Price		Factor	Total	
				Inst	allation	3.00	x	296.77	x	1.0320 =	\$918.80	·
3	01540	3011		EA	Disman	ling Of Scaffold ing Scaffold Pe	ing. U	sed To Set-up S	Cost In caffold	includes Both Erection Ar ing And Dismantle For F	Return,	\$149.78
				Inst	allation	Quantity 6.00	x	Unit Price 24.19	x	Factor 1.0320 =	Total \$149.78	
4	01590	1154		DAY		scopic Boom Li		24.10				\$1,646.08
						Quantity	••	Unit Price		Factor	Total	
			· .	Inst	allation	6.00	х	265.84	x	1.0320 =	\$1,646.08	
5	01590	9104		DAY	14 Ton	Lift Hydraulic Ci	ane, V	Vith Full-Time O	perator	•		\$2,401.07
				Inct	allation	Quantity		Unit Price		Factor 1.0320 ⁼	Total \$2,401.07	
6	01660	1002		CY		3.00 Material Via Els	X	775.54 Per CY Of Mate	X	1,0320		\$6,868.99
0	01000	1002			allation	Quantity	x x	Unit Price	X	Factor 1.0320 =	Total \$6,868.99	•••
7	01660	2001		SF		5,200.00				niture, General, Desks, 1	ables,	\$891.65
					File Cat Comput Less Th	inets (Full). Ch	airs, S Office	torage Boxes, B Area); Not To B	ookshe	Ives, Office Equipment When Amount Of Furni Factor	And ture Is Total	
				Inst	allation	3,600.00	х	0.24	X	1.0320 =	\$891.65	<u> </u>
8	01660	4002		CY	Rubbish	h Handling Via E	levato	or, Per CY Of Ma	aterial F		Tatal	\$2,753.38
	-			Inst	allation	Quantity 2,300.00	x	Unit Price 1.16	<u>x</u>	Factor 1.0320 =	Total \$2,753.38	
9	01740	1111		CSF	Clean M	liscellaneous S	urface	s, Wipe Down V	Vith Mile	d Detergent		\$3,904.06
	10 M 1			Inst	allation	Quantity 780.00	x	Unit Price 4.85	. X	Factor 1.0320 =	Total \$3,904.06	
	· · · · · ·									Subtotal for (01 \$2	23,016.81
Sec	tion 05	e se de la	109-20-5	\$ 	and the second	and the second second	(1) in the			and the second		
0.1.5-0.04783	05120	1311		TON	0-10 LB	/LF Rolled Sha	pe Ste	el Angles				\$28,813.51
						Quantity		Unit Price		Factor	Total	
					allation	4.50	х	6,204.46	. X	1.0320 =	\$28,813.51	
11	05120	2201		LB	Column		p To 1		ach, A	36 Miscellaneous Steel	Items Total	\$996.91
				Ins	tallation	Quantity 600.00	x	Unit Price 1.61	x	Factor 1.0320 =	\$996.91	
12	05120	3432		LF	3/16" H	orizontal Fillet V	Velds,	Welded Up				\$2,077.00
				Ins	tallation	Quantity 580.00	x	Unit Price 3.47	x	Factor 1.0320 =	Total \$2,077.00	

Proposal Review - CSI Detail

Page 1 of 7

3/18/2008

Proposal Review - CSI Detail (Continued) Job Order Number: 07616 Job Order Name: PBSO - 911 Hardening

12.50.48DM D DBCO 011 Hardonin ~ .

	iew:	4007	1 200	- 911 Hardening					Dall		\$350.0
13	05502	1007		EA 1/2" Dia		.ong vv	edge Anchor Ex Unit Price	pansion	Factor	Total	\$000.C
				Installation	Quantity 64.00	×	5.30	x	1.0320 =	\$350.05	
14	05504	1002		EA 1/2" Dia	meter x 3" Long	A325	Hex Bolt		•		\$1,404.3
					Quantity		Unit Price		Factor	Total	
		-		Installation	280.00	X	4.86	X	1.0320 =	\$1,404.35	
						2			Subtotal fo	r 05 \$3	3,641.8
Sec	tion 06				an or break the	andra sana Abasang		rara la la	in San Sur Lington		
15	06110	9313		LF 1"x4" (2	.5cm x 10cm) L	ight Fra	aming And Furri	ng			\$243.5
				Installation	Quantity		Unit Price		Factor 1 0320 =	Total \$243.55	
	00400	4205			200.00	X	1.18	X Iné Nota	1.0020		16,957.
16	06160	1205		SF 5/8" (16		; Piywo	Unit Price	ing Note	Applied To Wall S Factor	Total	510,557.0
				Installation	Quantity 15,800.00	x	1.04	x	1.0320 =	\$16,957.82	
17	06160	1205	1233	SF For App			s, Joists, Or Raf	ters, Add	1		\$1,467.
					Quantity		Unit Price		Factor	Total	
				Installation	15,800.00	х	0.09	х	1.0320 =	\$1,467.50	
18	06160	1205	1912	SF For Fire	Retardant Trea	itment,	Add				\$7,826.
				Installation	Quantity		Unit Price		Factor 1.0320 ⁼	Total \$7,826.69	
40	00440	0405			15,800.00	X	0.48	X			\$1,183.
79	06410	2125		EA 42"-48" solid ha door pa	rdwood face fra	mes, h	ardwood door fr	ames. H	Cabinet Note: Prefir ardwood veneer on	raised	ψ1,100.
					Quantity		Unit Price		Factor	Total \$1,028.92	•
				Installation Demolition	3.00 6.00	x x	332.34 24.91	x	1.0320 = 1.0320 =	\$154.24	
20	06415	1004		LF Plastic					cksplash Note: Up		\$192.
				deep	Quantity		Unit Price		Factor	Total	
				Installation	6.00	x	23.80	x	1.0320 =	\$147.37	
				Demolition	12.00	x	3.66	X	1.0320 =	\$45.33	
									Subtotal fo	or 06 \$2	7,871.
Sec	tion 07		ster serve	and the second second		3769. ₂					NATE: N
21	07920	2004		CLF Silicon	Caulk And Seal	, 3/8"x3	3/8" Joint				\$1,581.
				Installation	Quantity		Unit Price		Factor 1.0320 =	Total \$1,581.44	
				Installation	24.00	X	63.85	X			4 504
TURNA SER	an an the second second second second	NOT IN A REPORT OF THE	The state land of gal 2, the			NULLICE FOR T			Subtotal fo	pru/ \$	1,581.
Sec	tion 08	a an		Martine States			an a			4. C. 1997	· · · · ·
22	08110	1115		EA 3'x6'-8"	Through 7'-2"x4	1-3/4" [Deep Metal Door	r Frame,	16 Gauge		\$408.
				Installation	Quantity		Unit Price		Factor	Total \$357.98	
						х	173.44	×	1.0320 =	\$50.40	
					2.00	~	24 42		10320 =		
	08110	3335		Demolition	2.00	x Metal D	24.42	x	1.0320 =		\$729.
	08110	3335		Demolition	2.00 3/4" 16 Gauge I		loor (Unrated)	X		Total	\$729.
	08110	3335		Demolition	2.00 3/4" 16 Gauge Quantity	Metal D	·······	x	Factor 1.0320 =		\$729.
	08110	3335	· · · · · · · · · · · · · · · · · · ·	Demolition EA 3'x7'x1-	2.00 3/4" 16 Gauge I		oor (Unrated) Unit Price		Factor	Total	\$729.
23	08110	3335 6728		Demolition EA 3'x7'x1- Installation Demolition	2.00 3/4" 16 Gauge I Quantity 2.00 2.00 Steel Roll-Up Do	Metal C x x	Door (Unrated) Unit Price 338.86 14.65 23" Thick Door,	x x	Factor 1.0320 = 1.0320 = rive Light Weight A	Total \$699.41 \$30.24 nd Medium	
23				Demolition EA 3'x7'x1- Installation Demolition EA 8' x 8' S	2.00 3/4" 16 Gauge Quantity 2.00 2.00	Metal C x x	0oor (Unrated) Unit Price 338.86 14.65	x x	Factor 1.0320 = 1.0320 =	Total \$699.41 \$30.24	\$729. \$2,151.

2 of 7 age 3/18/2008

Proposal Review - CSI Detail (Continued)

Job Order Number: 07616

Job Order Name: PBSO - 911 Hardening

Review. PBSO - 911 Hardening 3/17/2008 12:59:48PM

Revi	iew:		PBSO	- 911 H	ardening	g - 3/17/2008	12:59	9:48PM				1.1
25	08710	9001		EA	Remov	ve And Reinstall I	Door Lo	ockset, Entrance	Ð			\$37.81
				Inst	allation	Quantity 2.00	X	Unit Price 18.32	X	Factor 1.0320 =	Total \$37.81	1
26	08710	9004		PR	Remov	e And Reinstall	Butts/H	inges				\$20.14
				Inst	allation	. Quantity 4.00	x	Unit Price 4.88	x	Factor 1.0320 =	Total \$20.14	
27	08710	9009		EA	Remov	e And Reinstall	Surface	Mounted Door	Closer	Or Holder		\$50.40
			- 	Inst	allation	Quantity 2.00	x	Unit Price 24.42	x	Factor 1.0320 =	Total \$50.40	
	<u></u>									Subtotal for 0	8 \$	3,398.2 [,]
Sec	tion 09											W.R. a.
28	09110	2003		SF	3-5/8"	Metal Stud Chan	nel, 16	" On Center, 20	Gauge	, With Tracks And Runn	ers	\$1,535.62
				Inst	allation	Quantity 960.00	x	Unit Price 1.55	x	Factor 1.0320 =	Total \$1,535.62	
29	09110	2005		SF	6" Met	al Framing Stud,	16" On	Center, 20 Ga	uge, W	ith Tracks And Runners	\$	45,145.87
				Inst	allation	Quantity 15,850.00	x	Unit Price 2.76	x	Factor 1.0320 ⁼	Total \$45,145.87	
30	09205	8105		LF	Corne	Bead, Vinyl						\$482.98

30	09205	8105	LF	Corner	Bead, Vinyl							\$482.98
					Quantity		Unit Price		Factor		Total	
			h	nstallation	520.00	х	0.90	х	1.0320	=	\$482.98	
31	09250	1103	SF	5/8" Dry	wall, One Layer	, One	Face On Wood	Or Meta	al Studs Or Fu	rring,	(16 mm)	\$13,044.48
					Quantity		Unit Price		Factor		Total	
			li li	nstallation	15,800.00	x	0.80	х	1.0320	=	\$13,044.48	
32	09250	4101	SF	Tape, S	packle And Fini	sh Dry	wall Walls Up To	o 10' He	eight	,		\$4,086.72
					Quantity		Unit Price		Factor		Total	
			li	nstallation	18,000.00	x	0.22	x	1.0320	=	\$4,086.72	
33	09250	4301	LF		packle And Fini corners.	sh Vei	tical Corners Up	To 10'	Height Note:	Inside	or outside	\$378.33
				-	Quantity		Unit Price		Factor		Total	
			li	nstallation	780.00	х	0.47	х	1.0320	=	\$378.33	
34	09511	2104	SF	2' x 4' x	5/8" Mineral Fit	er Aco	oustical Ceiling P	anels				\$6,076.42
					Quantity		Unit Price		Factor		Total	
			l.	nstallation	9,200.00	х	0.64	х	1.0320	=	\$6,076.42	
35	09540	1003	SF	T Bar C	eilings Suspens	ion Sy	stem 2'x 4', Star	dard 1	5/16"			\$10,443.84
					Quantity		Unit Price		Factor		Total	
			<u> </u>	nstallation	9,200.00	х	1.10	х	1.0320	=	\$10,443.84	
36	09650	3131	LF	1/8" Vir	yl Plastic Base,	4" Hig	h, All Colors					\$6,458.26
					Quantity		Unit Price		Factor		Total	
			. I	nstallation	4,200.00	x	1.24	x	1.0320		\$5,374.66	
			. E	Demolition	4,200.00	X	0.25	х	1.0320	=	\$1,083.60	
37	09720	2005	SF	0.022" \	Vinyl-Coated Wa	all Cov	ering, Semi-Rigi	d Vinyl/	Acrylic			\$7,925.76
					Quantity		Unit Price		Factor		Total	
			1	nstallation	0.00	x	2.18	x	1.0320		\$0.00	
				Demolition	12,000.00	x	0.64	х	1.0320	=	\$7,925.76	
38	09920	1415	SF	Paint In	terior Plaster/D	rywall,	1 Coat Primer, E	Brush/R	oller Work			\$8,544.96
					Quantity		Unit Price		Factor		Total	
			1	nstallation	36,000.00	x	0.23	х	1.0320	=	\$8,544.96	
39	09920	1417	SF	Paint In	terior Plaster/D	ywall,	2 Coats Paint, B	rush/R	oller Work			\$17,089.92

Total \$17,089.92 Unit Price Factor 1.0320 = Quantity Installation 0.46 36,000.00 Page 3 of 7 Proposal Review - CSI Detail 3/18/2008

Proposal Review - CSI Detail (Continued) Job Order Number: 07616

Job Order Name: PBSO - 911 Hardening

PBSO - 911 Hardening - 3/17/2008 12:59:48PM Review:

								Subtotal for 09	¢47	7,661.6
		:	Installation wallpaper remov	Quantity 12,000.00 /al.	×	Unit Price 0.40	x	Factor 1.0320 =	Total \$4,953.60	· .
45	09945	1701	SF Citrus St	ip, Single App	lication	IS				\$4,953.60
			Installation	Quantity 6,000.00	x	Unit Price 0.19	x	Factor 1.0320 =	Total \$1,176.48	;
44	09945	1202	SF Hand Wa	sh, Minor Rep	air Anc	I Light Sanding	Drywall S	Surfaces		\$1,176.4
			Installation	Quantity 4.00	x	Unit Price 27.48	x	Factor 1.0320 =	Total \$113.44	
43	09920	4313	EA Paint Inte	erior Door, One	e Face,	2 Coats Paint, I	Brush/Ro	oller Work		\$113.4
		· ·	Installation	Quantity 4.00	x	Unit Price 15.44	x	Factor 1.0320 =	Total \$63.74	
42	09920	4311	EA Paint Inte	rior Door, One	Face,	1 Coat Primer,	Brush/R	oller Work		\$63.7
			installation	Quantity 120.00	x	Unit Price 0.78	x	Factor 1.0320 =	Total \$96.60	
41	09920	4106	LF Paint Inte	rior Metal Fra	ne Anc	I Trim, 2 Coats I	Paint, Br	ush/Roller Work		\$96.6
	•		Installation	Quantity 120.00	×	Unit Price 0.36	x	Factor 1.0320 ⁼	Total \$44.58	
40	09920	4104	LF Paint Inte	rior Metal Fra	ne Anc	l Trim, 1 Coat P	rimer, Bi	rush/Roller Work		\$44.5

								Subtotal for 09	\$12	7,661.60
Sec	tion 15				1247-1967. 	en e	And S.			
46	15063	1603	LF 1/2" Insid	le Diameter Ty	ype L C	opper Tubing				\$536.64
				Quantity		Unit Price		Factor	Total	
			Installation	160.00	х	3.25	x	1.0320 =	\$536.64	
47	15063	1607	LF 1-1/2" Ins	side Diameter	Type L	Copper Tubing				\$1,750.27
				Quantity		Unit Price		Factor	Total	
			Installation	160.00	x	10.60	x	1.0320 =	\$1,750.27	
48	15063	2183	EA 1/2" Stra	ight Copper C	oupling					\$83.28
			,	Quantity		Unit Price		Factor	Total	
			Installation	6.00	х	13.45	x	1.0320 =	\$83.28	
49	15063	2187	EA 1-1/2" St	raight Copper	Couplir	ng				\$171.5
				Quantity		Unit Price		Factor	Total	
			Installation	6.00	х	27.71	x	1.0320 =	\$171.58	
50	15063	2233	EA 1/2" Cop	per Adapter, N	/lale	· · · · · · · · · · · · · · · · · · ·				\$27.1
				Quantity		Unit Price		Factor	Total	
			Installation	2.00	x	13.16	x	1.0320 =	\$27.16	
51	15063	2237	EA 1-1/2" Co	opper Adapter	, Male					\$69.0
				Quantity		Unit Price		Factor	Total	
			Installation	2.00	х	33.46	x	1.0320 =	\$69.06	
52	15064	6112	LF 3/4" Pipe	Schedule 40	PVC S	ocket Weld				\$359.9
				Quantity		Unit Price		Factor	Total	
			Installation	160.00	x	2.18	×	1.0320 =	\$359.96	
53	15064	6152	EA 3/4" 45 D	egree Elbow,	PVC S	chedule 40 Sock	et Weld			\$49.3
				Quantity		Unit Price		Factor	Total	
			Installation	6.00	х	7.97	x	1.0320 =	\$49.35	
54	15064	6232	EA 3/4" Red	ucing Insert, F	VC Sc	hedule 40 Socke	t Weld >	(Female/Male Thread		\$16.3
				Quantity		Unit Price		Factor	Total	
			Installation	2.00	x	7.93	x	1.0320 =	\$16.37	
						- <u></u>				
ronc	sal Ravie	w - CSI Detail								Page 4 of
20										•

3/18/2008

Proposal Review - CSI Deta

Proposal Review - CSI Detail (Continued)

Job Order Number: 07616

Job Order Name: PBSO - 911 Hardening

Review: PBSO - 911 Hardening - 3/17/2008 12:59:48PM

Revi	ew:		PBSO -	911 Ha	ardening -	3/17/2008	12:59	9:48PM					
55	15064	6332		EA	3/4" Unio	n, PVC Schedi	ule 40	Socket Weld					\$155.41
				Insta	llation	Quantity 11.00	x	Unit Price 13.69	x	Factor 1.0320	=	Total \$155.41	
56	15182	1102		LF	3/4" Dian	neter Pipe, 1/2"	' Thick	Fiberglass Insu	lation				\$607.64
						Quantity		Unit Price		Factor		Total	
				Insta	llation	160.00	x	3.68	х	1.0320	=	\$607.64	
57	15184	1004		LF		ric Unicellular			2" Thick		lexible		\$553.15
				Inote	allation	Quantity		Unit Price		Factor	-	Total \$553.15	
						160.00	x	3.35	X	1.0320			NAE 500 7
58	15190	6002		SF	1-1/2" Th	ick Rigid Duct,	Fibrou	us Glass Board V	Nith Foi	I Facing Vap	or Seal, 4		\$15,509.7
				lanta		Quantity		Unit Price		Factor	_	Total \$15,509.72	
					Illation	1,860.00	х	8.08	<u>х</u>	1.0320			
59	15661	2004		EA	3 Ton 13 capable o	SEER Air Coo of charging the Quantity	led Co syster	ndensing Unit N n with a 20' leng Unit Price	ote: Pre th of pip	echarged with bing. Factor	refrigera	nt Total	\$1,367.73
				Insta	Ilation	1.00	x	1,325.36	x	1.0320	=	\$1,367.77	
60	15661	8303		EA	3 Ton Co			Coil, Horizontal			·		\$409.0
00	10001	0000		27.	0 1011 00		orator	Unit Price		Factor		Total	•
				Insta	allation	Quantity	x	396.40	X	1.0320	=	\$409.08	
64	15720	1111	· · · · · · · · · · · · · · · · · · ·			1.00		sate Pump And 1					\$1,630.7
07	15720	1111		EA				I Discharge Pres Unit Price		Factor	Salion Ca	Total	φ1,000.1
				Insta	Ilation	1.00	x	1,580.22	х	1.0320	=	\$1,630.79	-
62	15773	1005		EA		ir Cooled Com Remote Conde		Room Air Conditi	ioner, D	irect Expansi	on Type,		\$26,472.2
						Quantity		Unit Price		Factor		Total	
	÷ · .				allation	1.00	X	24,285.79	x	1.0320		\$25,062.94	
					olition	1.00	x	1,365.60	x	1.0320		\$1,409.30	
63	15840	1217		LF	12" Rour Pressure		Sheet I	Metal Duct, Fact	ory Fab	ricated, Field Factor	Installed,	Low	\$2,224.9
				insta	allation	Quantity	v	Unit Price 8.02	x	1.0320	=	\$1,655.33	
					olition	200.00 200.00	x x	2.76	x	1.0320		\$569.66	
64	15871	4006		LF				egisters 225 - 49				ng	\$7,237.7
• •						Quantity		Unit Price		Factor		Total	
				Insta	allation	48.00	x	146.11	x	1.0320	=	\$7,237.70	
			<u></u>								tal for '	15 \$5	59,232.1
Sec	tion 16		an a		in station of the			rpation galaxy reaction for	Store and	gent an			
AND INCOMES IN DO	16101	1003		EA	Lock Out	/Tag Out Circu	it Brea	aker	WINESDOX SHITS-1010			· · · · ·	\$121.3
00	10101	1000		<u> </u>	LOOK OU	Quantity		Unit Price		Factor		Total	
				Insta	allation	8.00	x	14.70	x	1.0320	=	\$121.36	
66	16120	1265		MLF	3/c #12 /			HW), 600 V, St					\$10,890.3
00	10120	1205		1VILI	5/6 #12 /			Unit Price	ianaoa,	Factor		Total	• • • • • • • • • •
				Insta	allation	Quantity	~	1,677.49	. x	1.0320	=	\$10,387.02	
					olition	. 6.00 2.00	X X	243.85	x	1.0320		\$503.31	
67	16120	1524		MLF				RHH-RHW 600 V					\$1,131.7
0,					Conduit								
0,					Conduit	Quantity		Unit Price		Factor		Total \$1,131.76	

Proposal Review - CSI Detail

Page 5 of 7

3/18/2008

Proposal Review - CSI Detail (Continued) Job Order Number: 07616

Job Order Name: PBSO - 911 Hardening

PBSO - 911 Hardening - 3/17/2008 12:59:48PM Review:

68	16120	1565	PBSO - 911 MLF	= #6 AWG	Cable - Type	THHN-1		opper, Si	ngle Strande	d, Place	ed In	\$2,089.82
	. ·.	1		Conduit	Quantity		Unit Price		Factor		Total	
				nstallation	2.00	х	1,012.51	x	1.0320	=	\$2,089.82	
69	16131	2612	LF	3/4" EM	Conduit, Mou	Inted Ex	xposed On Flat	Wall				\$6,662.59
					Quantity		Unit Price		Factor		Total	
			1	nstallation	2,600.00	x	2.22	x	1.0320		\$5,956.70	
			[Demolition	1,200.00	х	0.57	X	1.0320	=	\$705.89	
70	16131	2652	EA	3/4" EM	F Set Screw Co	oupling,	Mounted Expos	sed On F	lat Wall			\$88.7
					Quantity		Unit Price		Factor		Total	
				nstallation	36.00	X	2.39	X	1.0320	=	\$88.79	
71	1613 1	2712	EA	3/4" EM	Insulated Bo	x Conne	ector With Set S	crew				\$163.3
					Quantity		Unit Price		Factor		Total	
			. I	nstallation	46.00	x	3.44	x	1.0320	=	\$163.30	
72	16134	3312	EA	3/4", 2 G	ang, Type FS,	Cast B	lox, Up To 1-5/8	" Deep				\$3,058.8
			~		Quantity		Unit Price		Factor		Total	
				nstallation	80.00	х	37.05	x	1.0320	=	\$3,058.85	
73	16134	3313	EA	1", 2 Ga	ng, Type FS, C	ast Box	к, Up To 1-5/8"	Deep				\$2,548.6
					Quantity		Unit Price		Factor		Total	
			1	nstallation	60.00	х	41.16	x	1.0320	=	\$2,548.63	
74	16140	1243	EA	20 A, 12	0 V Isolated G	round F	Receptacles, Du	plex				\$78.5
					Quantity		Unit Price		Factor		Total	
			I	nstallation	3.00	x	25.37	x	1.0320	= .	\$78.55	
75	16140	4111	EA	1 Gang S	Switch Plate							\$30.1
•••				-	Quantity		Unit Price		Factor		Total	
				nstallation	40.00	х	0.73	x	1.0320	. =	\$30.13	
76	16140	8001	EA	Remove		Recept	acle, Switch, Ou	utlet Or S	pecial Syste	m Devic	æ	\$2,130.8
					Quantity		Unit Price		Factor		Total	
			1	Installation	80.00	x	25.81	x	1.0320	=	\$2,130.87	
77	16170	1131	EA			ct Switc	h, NEMA 1, Hea	avy Duty,	With Fuses	, 240 V,	3 Phase	\$536.0
					Quantity		Unit Price		Factor		Total	
				Installation	2.00	X	259.73	x	1.0320	=	\$536.08	
78	16170	1271	EA	30 A. No			eavy Duty Disco	nnect Sv	vitch, 480 V,	3 Phase	9	\$874.8
					Quantity	,	Unit Price		Factor		Total	
			•	Installation	2.00	x	423.84	x	1.0320	=	\$874.81	
79	16450	1313	EA	Beam C			_ightning Protec	tion Svst				\$132.6
10	10:100			boarro	Quantity	oppo	Unit Price		Factor		Total	
				Installation	2.00	x	64.27	x	1.0320	=	\$132.65	
80	16450	1317	EA				htning Protection					\$108.0
00	10400	1017	LA			phei ris	-		Factor		Total	
				Installation	Quantity 2.00	x	Unit Price 52.37	x	1.0320		\$108.09	
04	10454	1004	···· · · · · · · · · · · · · · · · · ·									\$172.6
81	16451	1204	ML	- 6AWG		ea Sing	le Stranded Col	nuucioi	F t		Total	
				Installation	Quantity		Unit Price	v	Factor 1.0320		Total \$172.60	
	10544	4004			0.20	<u>X</u>	836.26	X				\$2,587.0
82	16514	1001	EA	Remove		∟ay-In	Fluorescent Ligi					
				Installation	Quantity		Unit Price		Factor		Total \$2,587.02	
				Installation	60.00	X	41.78		1.0320			
	40500	1901	EA	Remova	I And Reinstall	Of Exil	t Light Fixtures I	ncludes	Storage And	Cleanin	ıg	\$121.4
83	16530	1001		T CITIO V C			-					
83	16530			Installation	Quantity		Unit Price 29.42	x	Factor 1.0320		Total \$121.45	

Proposal Review - CSI Detail

Page 6 of 7 3/18/2008

Proposal Review - CSI Detail (Continued)

Job Order Number: 07616

Job Order Name: PBSO - 911 Hardening

Review: PBSO - 911 Hardening - 3/17/2008 12:59:48PM

Subtotal for 16

\$33,527.67

\$309,931.14

Proposal Review Total

This job order proposal total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding of the line totals and sub-totals.

Proposal Review - CSI Detail

Page 7 of 7 3/18/2008

DATE March 19, 2008	GC 06 - SBE Estimate					
Job# 07616 Loc# 108	CJC Bldg A, Administration, 3228 Gun Club Road PBSO - 911 Hardening					
SUBMITTED BY	Holt Contractors, Inc. 8161 NW 51st Place Coral Springs, FL 33067	Contract: R-2007-0947 Awarded: 06/19/2007				

Proposal Value:

\$ 309,931.14

Contractor/Sub-Contractor	Trade	SBE Status	SBE \$	% of Job	
Holt Contractors, Inc.	SBE-Non MWBE		309,931.14	309,931.14	
	Total estimate	SBE participation	1	100.00%	
	· · · · · · · · · · · · · · · · · · ·		0.00		
0%	Estimated	Participation	100%		

.

GC 06 - SBE Estimate



÷

Page 1 of 1 3/19/2008

REQUEST DATE: March 18, 2008	REQUESTED BY: Daniel Racette	PHONE#:
REQUEST DIVID. March 10, 4000		

PHONE#: (561) 233-2057

PROJECT TITLE: PBSO - 911 Hardening

Project No: 07616

LOCATION #: 108

LOCATION DESCRIPTION: CJC Bldg A, Administration, 3228 Gun Club RoadORIGINAL CONTRACT/ANNUAL AMOUNT:BCC RESOLUTION # / DATE:R-2007-0947 dated 06/19/2007

CSA/LOA/CHANGE ORDER AMOUNT:

CSA/LOA/CHANGE ORDER NUMBER: Work Order #: 08-071 CONTRACTOR/CONSULTANT NAME: Holt Contractors, Inc.

PROVIDE A BRIEF STATEMENT OF THE SCOPE OF SERVICES TO BE PROVIDED BY THE CONSULTANT/CONTRACTOR:

Provide an LRDM review of the 911 space.

WILL THIS AMENDMENT CHANGE THE ESTIMATED COST OF THE PROJECT? Yes IF YES, PROVIDE ESTIMATES OF THE NEW COSTS:

TOTAL:	\$351.573.22	
	30,993.11	
	0.00	
	6,000.00	
R	4,648.97	1.5% WORK ORDER AMOUNT FOR TGG FEE
	309,931.14	
		ER 4,648.97 6,000.00 0.00 30,993.11

* By signing this BAS your department agrees to these staff costs and your account will be charged upon receipt of this BAS by FD&O. Unless there is a change in the scope of work, no additional staff charges will be billed.

BUDGET ACCOUNT NUMBERS (IDENTIFY ALL SOURCES): FUNDING SOURCE (CHECK ALL THAT APPLY)

3804-411-8405-01-4907

AD VALOREM

FEDERAL/DAVIS BACON

SUPPLEMENTAL AGREEMENT TO BE APPROVED BY:

BCC (WO > \$100,000)

3-19 08

ANTICIPATED DATE OF APPROVAL:ASAP

BAS APPROVED BY

DATE:

OTHER

ENCUMBRANCE NUMBER:

MAR 1 9 2008

huenicpale hærdenheg suburit B405-01

ATTACHMENT #5